



Published by
NAVY
Navy Publications
Distribution



AC WIRING LAYOUT


SEE WIRING DIAGRAM

TO SHORE




THE CASINGS OF ALL AP
BOXES, WHICH IN TURN
DO NOT, IN ANY INSTANCE
OR HULL G

Return to T. Weymouth
"Wey-70-60"



NOTES -

- 1- ALL WIRES ARE #14 UNLESS SHOWN OTHERWISE
- 2- RETURN NEGATIVE WIRES ARE BLACK SHOWN -> B
- 3- HULL IS NOT TO BE USED AS RETURN WIRE
- 4- WIRES ARE TO BE CABLED WHERE POSSIBLE
- 5- ALL HOLES THROUGH METALS ARE TO BE BUSHED
- 6- ALL JOINTS ARE TO BE SOLDERED
- 7- REFER TO MOTOR WIRING DIAGRAMS FOR MOTOR AUXILIARIES



SEE TELETYPE
27516

12 V DC WIRING DIAGRAM

SCALE	
DATE	
DESIGNED BY	
CHECKED BY	
APPROVED BY	
REVISIONS	